Quote #17028716-2

Standard Freight Included: 15084 Zip Code

All Hardware and Anchors Included

Doors, Dividers, Pilasters Included



Powder Coat 3 year warranty

Delivered in 3-6 business days (Quick Ship colors only); Standard colors in 12-18 business days \$1,842.79

Price includes materials and hardware

Product Info | Color Chart

Date: 03/06/2024



Plastic Laminate 2 year warranty

Delivered in 5-10 business days

\$2,009.18

Price includes materials and hardware

Product Info | Color Chart



Solid Plastic 25 year warranty

Delivered in 9-11 business days

\$2,781.25

Price includes materials and hardware

Product Info | Color Chart



Stainless Steel 5 year warranty

Delivered in 3-6 business days

\$3,456.95

Price includes materials and hardware <u>Product Info</u> | <u>Color Chart</u>



Phenolic 25 year warranty

Delivered in 6-10 business days


\$3,576.58

Price includes materials and hardware <u>Product Info</u> | <u>Color Chart</u>



SOLID PLASTIC COLOR CARD

*Delivered in 6-9 Business Days






Drawing Notes

- · Compartment widths on drawings are shown at center line of panels.
- · Compartment depths on drawings are shown from front face of pilaster to finished wall.
- · Cut headrail in field to suit (if applicable).
- "X" on drawings indicates that backing is required.
- · Fabrication will not commence until approval has been received.
- · Material supplied will conform to the dimensions indicated on drawings.
- · Scale of drawings none.
- Improve on drawings indicates location of pilaster reinforcing channel(s).

hadrian-inc.com PAGE 1 0F 7


Project Title 17028716 **Distributor** Fry Specialty Inc. Created By Rob Fry Last edit date 03/07/2024 Drawing Title MEN 03/07/2024 Project Number P0693483 Date Printed






 Project Title
 17028716
 Created By
 Rob Fry
 Last edit date
 03/08/2024
 Distributor
 Fry Specialty Inc.

 Drawing Title
 WOMEN
 Date Printed
 03/08/2024
 Project Number
 P0693483







Material Specification

HEADRAIL BRACED - SOLID PLASTIC TOILET PARTITIONS - STANDARD

1.01 Construction Features

Doors, panels and pilasters shall be certified Class B polyethylene solid plastic. The material shall contain no foaming agents, which can cause the formation of air pockets. The self-lubricating surface is resistant to marking and can be maintained effectively with ordinary household cleaners. Material is ideal for toilet partition installations, especially in high abuse and high moisture environments.

1.02 Doors

Shall be (25mm) 1" thick by (1397mm) 55" high and straight cut with fine radius edges.

1.03 Panels

Shall be (25mm) 1" thick by (1397mm) 55" high and straight cut with fine radius edges.

1.04 Pilasters

Shall be (25mm) 1" thick by (2083mm) 82" high and straight cut with fine radius edges.

1.05 Headrail

Shall be 32mm (1.25") by 44mm (1.75") extruded anodized aluminum with anti-grip design. Wall thickness to be 1.5mm (0.060") and shall be securely attached to wall and pilasters with manufacturer's fittings in such a way as to make a rigid installation. All joints in headrails shall be made at a pilaster.

1.06 Pilaster Fastening Method

Pilasters shall be securely and rigidly fastened to the floor with 3" (76mm) high stainless steel anchor shoes. Three heavy-duty aluminum brackets shall be used at the pilaster to wall connection.

1.07 Hardware and Fittings

Doors are installed with 1/8" thick heavy extruded clear anodized aluminum hinges, which wrap around both the door and pilaster. Hinges are fastened to door and pilaster with tamper-proof 6-lobe security head stainless steel thru-bolts and fastened to the edge of the door and pilaster with a #10 x 1" screw. Top hinges have adjustable nylon cams.

Strike-keeper and throw latch are extruded clear anodized aluminum.

The combined stop and keeper shall have a 19mm (0.75") diameter bumper locked in place. Finish to match other hardware items. Doors shall be fitted with a zinc die cast, #4 brushed combined coat hook and bumper. Fasteners are theft-proof 6-lobe security head stainless steel screws. Hadrian door hardware meets ADA and Canadian barrier-free requirements.

Three heavy-duty aluminum brackets are used at the panel to wall connection and a full-height continuous aluminum channel is used at the panel to pilaster connection.

1.08 Finish


Doors, panels and pilasters shall be certified Class B polyethylene with uniform color throughout. Color shall be as selected from Hadrian's color card.

This specification applies to room(s): MEN, WOMEN

hadrian-inc.com



Plastic Toilet Partitions Standard Series - Headrail Braced - 14" [356mm] AFF Aluminum Channels & Brackets - Aluminum Surface Latch & Wrap Hinge



Important Notes:

Refer to final drawings for wood blocking information. Wood blocking is critical to ensure a rigid installation. See material specifications for material and hardware finishes.

hadrian-inc.com

^{*}Above finish floor dimensions may vary due to floor level and cam position



Warranty Information

Hadrian Manufacturing Inc. ("Hadrian") provides the following warranty with respect to the Hadrian product(s) supplied for the project indicated above.

Subject to the terms set out herein, the product(s) are warranted against defects in material and workmanship from the date of receipt by the authorized Hadrian distributor for the warranty period outlined below:

Powder Coated Toilet Partitions	3 years
Stainless Steel Toilet Partitions	5 years
Solid Plastic Toilet Partitions	25 years
Phenolic Black Core Toilet Partitions	25 years
Emperor (corridor) Lockers	2 years
Gladiator (athletic) Lockers	5 years
Replacement Front Lockers	2 years
Boot Racks	1 year

The warranty is for Hadrian material only and excludes damages caused by installation errors, vandalism, improper usage, improper maintenance, exposure to harsh environments or chemicals (such as chlorine, bromine, etc.) or failure of the building structure to adequately support the product. Site preparations (i.e. wood blocking, etc.) must meet final drawing specifications and Hadrian's recommended maintenance procedure must be followed.

The exclusive remedy under this warranty shall, at Hadrian's discretion, be replacement or repair of the defective material. Hadrian will not pay any removal, installation or other labor costs associated with the repair or replacement. Replacement material will be warranted for the unused portion of the original warranty period.

No warranty of merchantability or fitness for a particular purpose is made or implied. In no event shall Hadrian be liable for any other costs or damages, including loss of profit, loss of revenue, indirect, incidental, special or consequential damages howsoever arising, whether under warranty, contract, statute, tort, equity or otherwise.

This warranty extends only to the original authorized Hadrian customer and is non-transferable. Warranty claims must be made during the applicable warranty period and initiated by contacting Hadrian at the following coordinates: USA: 440-942-9118 / CANADA: 905-333-0300.

The foregoing constitutes the entire warranty given by Hadrian and no one is authorized to change or expand this warranty on behalf of Hadrian.



Hadrian Manufacturing Inc., 965 Syscon Road, Burlington, ON, L7L 5S3 T: 905-333-0300 F: 905-333-1841 Hadrian Manufacturing Inc., 2550 - 61 Avenue SE, Calgary, AB, T2C 4V2 T: 905-333-0300 F: 905-333-1841 Hadrian Inc., 7420 Clover Avenue, Mentor, OH, 44060 T: 440-942-9118 F: 440-942-9618 Hadrian Inc., 3602 West Washington Street, Suite 200, Phoenix, AZ, 85009 T: 440-942-9118 F: 440-942-9618

08/2023



Maintenance Procedure

FOR SOLID PLASTIC

MAINTENANCE OF YOUR TOILET PARTITIONS SHOULD BE A PART OF YOUR REGULAR BUILDING PREVENTIVE MAINTENANCE PROCEDURE

- 1. Tighten any screws that have become loose due to vibrational forces or attempted vandalism.
- 2. Be sure the surfaces are dry after being cleaned and rinsed with clear water (when required).
- 3. Partitions exposed to severe humidity should be washed and dried as needed.
- 4. Periodically, remove any dirt, grime or foreign matter with a soft cloth.
- 5. Where surfaces reveal spotting resulting from hand perspiration, soil, or grease, a thorough cleaning with warm water and a mild detergent (i.e. Ivory Soap), followed by rinsing, and removal of excess moisture, will renew the clean even surface, providing a pleasant sanitary appearance. (Use of cleaning agents containing abrasives such as household cleaning powder, steel wool, and harsh detergents or acids ARE NOT RECOMMENDED).
- 6. For areas of stubborn graffiti, commercial graffiti removers can be used.
- 7. To maintain the brilliance of hardware, these components can be periodically improved by an application of non-abrasive cleaner with a damp cloth.
- 8. If your partitions have a continuous hinge, regular application of an LPS II or an industrial type, non-drying lubricant is recommended.
- 9. The appearance of scratches may be minimized by burnishing the blemish with a smooth, rounded object such as a spoon. For best results, apply slight pressure in a parallel motion to the scratch.

hadrian-inc.com PAGE 7 0F 7